



# RECALL

**SCOTT SPEEDSTER 40 / SPEEDSTER 50 / SPEEDSTER GRAVEL 40 EQ /  
SPEEDSTER GRAVEL 50 / CONTESSA SPEEDSTER GRAVEL 35 MY22**

**HAZARD: FORK STEERER TUBE CAN BREAK WITHOUT WARNING**

Date: 16th January 2023

In cooperation with national recall authorities, Scott recalls certain Scott Speedster, Speedster Gravel, Contessa Speedster Gravel, 2022 bikes. Consumers should stop using recalled products immediately unless otherwise instructed. It is illegal to resell or attempt to resell a recalled consumer product.



Speedster 40



Speedster 50



Speedster Gravel 40 EQ



Speedster Gravel 50



Contessa Speedster Gravel 35



\*Speedster models not listed below are not affected by this recall

286437	Speedster 40 (EU)	286466	Speedster Gravel 50 (EU)
286438	Speedster 50 (EU)	286471	Speedster Gravel 40 EQ (CN)
286442	Speedster 40 (CN)	286465	Speedster Gravel 40 EQ (EU)
286443	Speedster 50 (CN)	286490	Contessa Speedster Gravel 35 (EU)
286472	Speedster Gravel 50 (CN)	286493	Contessa Speedster Gravel 35 (CN)

**UNITS SOLD: 1985**

**INCIDENTS: SCOTT INTERNAL TESTING FOUND TRACES OF CRACKING WITHIN THE FORK STEERER. NO CASE OF INJURY OR BREAKAGE HAS BEEN REPORTED IN THE MARKET.**

**SOLD AT: AUTHORIZED SCOTT DEALERS FROM OCTOBER 2021 TO MARCH 2022.**

**MADE IN: CHINA & HUNGARY**

**REMEDY: CONSUMERS IN POSSESSION OF A RECALLED SCOTT SPEEDSTER 40 & 50 / SPEEDSTER GRAVEL 40EQ & 50 / CONTESSA SPEEDSTER GRAVEL 35 SHOULD IMMEDIATELY STOP USING THE BICYCLE, AND RETURN IT TO AN AUTHORIZED SCOTT DEALER FOR A FREE REPLACEMENT FORK.**

**CONSUMER CONTACT:**

**FOR ADDITIONAL INFORMATION, PLEASE CONTACT SCOTT AT  
RECALL@SCOTT-SPORTS.COM  
TEL: +41 264 60 19 00**